





Puniversity of Toronto	Department of Computer Science
Premature Shutdown Scenario	
Cause of error	
Magnetic sensor on each leg senses to	uchdown
Legs unfold at 1500m above surface	
software accepts transient signals on to	ouchdown sensors during unfolding
Factors	
System requirement to ignore the trans	ient signals
But the software requirements did not d	lescribe the effect
Engineers present at code inspection di	idn't understand the effect
Not caught in testing because:	
Unit testing didn't include the transients	3
Sensors improperly wired during integra	ation tests (no touchdown detected!)
Result of error	
Engines shut down before spacecraft ha	as landed
estimated at 40m above surface, travelli	ing at 13 m/s
estimated impact velocity 22m/s (spacecraft would not survive this)	
nominal touchdown velocity 2.4m/s	
© 2008 Steve Easterbrook. This presentation is available free for non-commercial use with attribution under a creative commons license.	

























